

Attachment of signs, fences, cables and winches to a tree is not permitted as it causes direct damage to a tree and promotes decay

Parking of heavy vehicles and cars must not be allowed within the Tree Protection Zone as this may cause compaction and oil contamination

Fires should not be lit in the vicinity of trees. Burning by flames can cause damage and disease

Damage to limbs must be avoided. Ragged wounds speed infection

Protective fencing must be erected in accordance with AS4970 - 2009

Storage of materials within the Tree Protection Zone causes compaction and root suffocation

Spilling of diesel oil, chemicals and cement within the Tree Protection Zone may cause root death

Lowering ground level severs roots causing severe dieback or death of a tree

Raising ground levels even for only a few weeks and by only centimetres can suffocate roots, causing severe dieback

Trenches dug within the Tree Protection Zone severs roots, causing instability and crown dieback. Refer to SP.107 for installation of service trench.

NOTES:

1. When working around trees protection is foremost. Best practice standards and AS4970-2009 (Protection of Trees on Development Sites) must be adhered to at all times


2. All work around trees should adhere to any approved plans produced by a qualified professional

REVISIONS					
AMENDMENT	INITIALS	DATE	AMENDMENT	INITIALS	DATE
F				L	
E				K	
D				J	
C	Notes Altered			I	
B	Notes Altered			H	
A	ORIGINAL ISSUE			G	

IPSWICH CITY COUNCIL
 45 Rodenck St
 P.O. Box 191
 Ipswich QLD 4305
 Australia

Tel (07) 3810 7894
 Tel (07) 3810 7927
 Fax (07) 3810 7950

APPROVED



CHIEF OPERATING OFFICER (WPR)

DATE 29-7-13

STANDARD DRAWING

TREE PROTECTION REQUIREMENTS

PARKS

SP.11

REV: C DRAWER: 100